

Tire Exception Report


Units Inspected: 6

Tires Inspected	Tires with Exceptions	Dual Exceptions	Tires with Other Exceptions
48	67% (32)	25% (6)	0% (0)


Summary by Wheel Positions

	Steer	Drive	Trail	All
Avg. Tread	-	-	9	9
Avg. Pressure	-	-	86	86
Avg. % Inflated	-	-	82%	82%

Top 5 Wear Conditions



Inflation Distribution



Tires with Wear Conditions

20.8% (10)

Tires without Wear Conditions

79.2% (38)


Unit 40312

Tires with Exceptions

Position	Conditions	Valve	Brand	Product Line	Size	Load Range	Images	Comments
1LI		Flow Through			295/75R22.5			
2RO	RTD Edge Lifting	Flow Through			295/75R22.5	G	View	tread lifting
1RO		Flow Through			295/75R22.5		View	

Dual Exceptions

Position	Condition
1L	Mismatched Dual
1R	Mismatched Dual




Unit 40310

Tires with Exceptions

Position	Conditions	Valve	Brand	Product Line	Size	Load Range	Images	Comments
1LO	Weathering/Ozone Cracking	Flow Through			295/75R22.5		View	
1LI		Missing Cap			295/75R22.5			
2LO	Diagonal Wear	PSI System			295/75R22.5		View	
2LI		PSI System			295/75R22.5			
2RO	RTD Edge Lifting	Flow Through			295/75R22.5		View	
2RI	RTD Edge Lifting	Flow Through			295/75R22.5		View	
1RO	Chipping/Chunking Tread	Flow Through			295/75R22.5		View	

Dual Exceptions


Position	Condition
2L	Mismatched Dual



Unit 41972

Dual Exceptions

Position	Condition
1L	Mismatched Dual




Unit 40080

 [View Images](#)

Tires with Exceptions

Position	Conditions	Valve	Brand	Product Line	Size	Load Range	Images	Comments
1LO	RTD Edge Lifting	Flow Through			295/75R22.5		View	
1LI		Flow Through			295/75R22.5		View	nail in tread
2LO		Flow Through			295/75R22.5			
2LI	RTD Edge Lifting	Flow Through			295/75R22.5		View	
2RO		Flow Through			295/75R22.5			
2RI		Flow Through			295/75R22.5			
1RO		Missing Cap			295/75R22.5		View	curb rash, shoulder chipping
1RI		Missing Cap			295/75R22.5			




Unit 40313

Tires with Exceptions

Position	Conditions	Valve	Brand	Product Line	Size	Load Range	Images	Comments
1LI		Flow Through						
2LO	Diagonal Wear	Flow Through					View	
2LI		Flow Through						
2RO		Flow Through						
2RI		Flow Through						
1RI		Flow Through						

Dual Exceptions

Position	Condition
2L	Mismatched Dual



Unit 40328

Tires with Exceptions

Position	Conditions	Valve	Brand	Product Line	Size	Load Range	Images	Comments
1LO	RTD Edge Lifting				295/75R22.5		View	
1LI					295/75R22.5			
2LO					295/75R22.5			
2LI					295/75R22.5			
2RO					295/75R22.5			
2RI					295/75R22.5			
1RO					295/75R22.5			
1RI					295/75R22.5			

Dual Exceptions

Position	Condition
2L	Mismatched Dual

